

Annual Statement

Eddyville Charter School certifies the following:

1. Responsible Persons

The person responsible for implementing and administering the Healthy and Safe Schools (HASS) Plan is:

Name: Stacy Knudson
Position Title: Superintendent / K-12 Principal Title IX Coordinator
Phone Number: 541-875-2942
Email Address: stacy.knudson@lincoln.k12.or.us
Mailing Address: 1 Eddyville School Rd, Eddyville, OR 97343

The person who is the designated Integrated Pest Management (IPM) Coordinator is:

Name: Danny Wheeler
Position Title: Facility Director
Phone Number: 541-974-5734
Email Address: danny.wheeler@lincoln.k12.or.us
Mailing Address: 1 Eddyville School Rd, Eddyville, OR 97343

The person responsible for Asbestos Hazard Emergency Response Act (AHERA) information is:

Name: Missy Endicott
Position Title: Administrative Assistant, Human Resources, Business Manager
Phone Number: 541-875-2941 ext 110
Email Address: missy.endicott@lincoln.k12.or.us
Mailing Address: 1 Eddyville School Rd, Eddyville, OR 97343

2. Copies of the Healthy and Safe Schools Plan

Copies of the plan are available at each of the following locations:

- 1 Eddyville School Rd, Eddyville, OR 97343
- <http://www.eddyvillecharterschool.org/>

3. Testing Certification

Eddyville Charter School certifies that it is in compliance with all plan components, including any and all testing required by any part of the plan.

4. Testing Results

Eddyville Charter School is current with all required testing as of the date of this document. Test results can be found on the Eddyville Charter School website at <http://www.eddyvillecharterschool.org/>. Eddyville Charter School will also use current district email lists or communications programs to provide final test results to staff, students, parents of minor students, and other members of their community. This includes providing actual final test results or providing direct access to final test results through

7. Radon Testing Summary

Eddyville Charter School has completed radon testing at the following buildings this year and is providing the following summary:

Facility Name	Building Identification Number (BIN)	Number of radon tests conducted	Number of tests that exceed limits	Number of tests that exceed limits after remediation	Number of sites where remediation is still in process
Eddyville Charter School	Music Room	1	0	NA	0
Eddyville Charter School	Music Room (Dup)	1	0	NA	0
Eddyville Charter School	Room 55	1	0	NA	0
Eddyville Charter School	Room 55 (Dup)	1	0	NA	0
Eddyville Charter School	Room 54	1	0	NA	0
Eddyville Charter School	Room 54 (Dup)	1	0	NA	0
Eddyville Charter School	Room 49	1	0	NA	0
Eddyville Charter School	Room 49 (Dup)	1	0	NA	0

I certify that the above information is true and accurate to the best of my knowledge.

Danny Wheeler	Facility Director	05/25/2022
<i>Electronic signature of authorized representative</i>	Title	Date of Annual Certification